



IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification Scheme for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: IECEx BVS S0001 issue No.: 0 Certificate history: _____

Status: **Current** Date of Issue: 2010-08-12

Applicant: **thuba Ltd.**
Blauensteinerstrasse 16
4015 Basel
Switzerland

Type of Service: **Repair and Overhaul according to IEC 60079-19**

Type of Protection: Dusts to IEC 61241-1
Flameproof Enclosure "d"
Increased Safety "e"
Intrinsic Safety "i"
Other
Pressurisation "p"
Type of Protection "n"

Scope of Service: **Repair and overhaul of apparatus type of protection Ex d, Ex e, Ex px, Ex pz, Ex nA, Ex nR, Ex t/tD, Ex pD, Control devices Ex i, Ex iD and trace heating systems**

Locations covered by this Certificate: **thuba Ltd.**
Stockbrunnenrain 9
4123 Allschwil
Switzerland

Facility Audit Report: DE/BVS/FAR10.0001/00

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx Certification Body: Dr. Michael Wittler

Position: Head of Expert Body

Signature: 

Date: 12.08.2010

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting the Official IECEx Website.

Certificate issued by:

DEKRA EXAM GmbH
Dinnendahlstrasse 9
44809 Bochum
Germany

